Oil Field Environmental Incident Summary

Incident: 20160508132653 Date/Time of Notice: 05/08/2016 13:26 Responsible Party: Basin Transload and Summit Midstream Well Operator: Well Name: Basin Transload Stampede Field Name: Well File #: Date Incident: 5/8/2016 Time Incident: 09:07 Facility ID Number: **BURKE Twp:** 162 **Rna**: 93 **Sec:** 3 County: Location Description: 10154 93rd Ave NW Columbus, ND 58727 (Stampede) Submitted By: James Opitz Received By: Contact Person: James Opitz 10154 93rd Ave NW Columbus, ND 58727 General Land Use: Well/Facility Site Affected Medium: Well/Facility Soil 400 Feet Distance Nearest Occupied Building: Distance Nearest Water Well: 400 Feet Type of Incident: Tank Overflow Release Contained in Dike: Yes - Within Dike Reported to NRC: Yes Spilled Units Recovered Units Followup **Units** Oil 100 **Gallons Brine** Other **Description of Other Released Contaminant:** Crude oil Inspected: Written Report Received: Clean Up Concluded: Risk Evaluation: Low Areal Extent:

Potential Environmental Impacts:

low

Action Taken or Planned:

operations were stopped (estop pressed), valves closed, and containment of spill inside of containment dike ensured.

contacted Summit Midstream informed them of the leak from their tank.

began monitoring containment area

Wastes Disposal Location:

Agencies Involved: 911

NDDOH NRC

Burke county emergency management

USDOT pipeline safety

Updates

Date: 5/9/2016 Status: Reviewed - Follow-up Required Author: O'Gorman, Brian

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release, due to a tank overflow, remained within diking according to the report. Since this is a loading station, further follow-up is needed.

Date: 5/11/2016 Status: Inspection Author: Martin, Russell

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Duplicate report for incident #20160509083528. See that report for inspection and further details.